


HOZELOCK SPRAYERS

'o' rings in the shuttle assembly have been converted to viton seals for greater chemical resistance. All other seals remain nitrile.

Nozzle and 'o' ring shoulder increased to eliminate discharge from rear of nozzle.

Dip tube shortened to fit flush with the base of the container.



Modified cover and locking mechanism to improve lock-on facility at all pressures.

Plunger rod shortened to avoid possible contact with non-return valve.



BEFORE



AFTER

